## **435 - BUILDING PROJECTS**

		CES	GFS	KHS	LLS	SES	BMS	CMS	SHS	DISTRICT	TOTAL
Sump pump bottom of stair case (s	torm water)	6,500									6,500
Door & hardware replacement gym	n & café	18,300									18,300
Library/Computer room replace co	oling unit	13,000									13,000
VFD for boiler room with controls			20,000								20,000
Room 201 cooling unit upgrade			11,000								11,000
Café floor -replace				70,000							70,000
Pneumatic zone controls					9,646						9,646
(2) Chiller control panels adaptivies	w upgrades					56,870					56,870
Room 238 Split System							13,450				13,450
Air handler unit controls upgrade p	ool boiler room								9,000		9,000
Carpenter shop roof top unit instal	lation								4500		4,500
Security - interior cameras										50000	50,000
	FY21 BOE Proposed Budget	37,800	31,000	70,000	9,646	56,870	13,450	-	13,500	50,000	\$ 282,266

# ANTINOZZI REPORT - OPERATING YEAR 1 (435 BUILDING PROJECTS)

	CES	GFS	KHS	LLS	SES	BMS	CMS	SHS	DISTRICT		TOTAL
PRIORITY 1 - Life Safety										\$	392,242
Speakers to Gym and Cafeteria	13,131										13,131
Firestop penetration Equipment Room	394	263	525	525	328			985			3,020
Install visitor management system	6,818	6,566	6,566	6,566	6,566	6,566		6,566			46,214
IP front door airphone system	<del>-</del>	<del>7,879</del> -	<del>7,879</del> -	<del>7,879</del> -	<del>7,879</del>			<del>9,454</del>		l —	<del>40,970</del>
Protective cover canopy café entrance			29,249								29,249
Metal/concrete stairs remove and replace			13,131								13,131
Metal stairs treads/nosing repair and replace			11,326								11,326
PA speakers			10,505								10,505
Accessible signage throughout building			65,655								65,655
Wood stairs repair and replace (auditorium)					19,697						19,697
Repair outdoor artistic traffic control barricades					39,393						39,393
(2) Light poles repair and replace					7,222						7,222
Repair and replace rooftop sectional barrier fencing					31,514						31,514
Area of Refuge sign					1,313						1,313
Health Suite sign					394						394
Update metal catwalks auditorium								65,655			65,655
Stainless steel handrails natatorium								21,692			21,692
INERGEN fire suppression system (MDF Closet)								<del>29,545</del>		l —	<del>29,545</del>
Add speakers and clocks								13,131			13,131

<del>-</del>											
<del>-</del>	CES	GFS	KHS	LLS	SES	BMS	CMS	SHS	DISTRICT	1	TOTAL
PRIORITY 2 - Educational Environment										\$	132,755
Wireless access point mechanical spaces	4,202	6,303	10,505	2,101	2,101			12,606			37,818
2. Air compressor replacement boiler room								26,262			26,262
3. Wireless clock system	34,141										34,141
4. IT rack and server grounding	3,283	3,414	3,414	3,939	1,313			5,252			20,615
5. Backup pump addition (Heat loop)	2,758										2,758
6. Backup pump addition (Domestic HW)	9,848										9,848
7. Gypsum board replacement Door 292								1,313			1,313
PRIORITY 3 - Building Envelope										\$	308,908
1. Repair roof expansion joints	26,262										26,262
2. Asphalt shingles replacement (Library)		41,363									41,363
3. Investigate cause of roof bubbling and repair				65,655							65,655
4. Exterior wall repair		9,848									9,848
5. Roof drain repair	9,848										9,848
6. Trench drain and drywell					9,848						9,848
7. Masonry anchorage and reinforcing					32,828						32,828
8. Grout and seal metal exterior door frames								657			657
9. Repair metal wall panels (gym and auditorium)								32,828			32,828
10. Stucco on auditorium exterior					26,262						26,262
11.Repair/replace lintels (Door C8 and C17)								19,697			19,697
12. Masonry cleaning by exterior Door 13						13,131					13,131
13.Cooling Tower - replace valve actuators					20,681						20,681
Facilities Accepted Antinozzi Year 1 Recommendations	110,685	67,757	150,876	78,786	199,460	19,697	-	206,644	-	\$	833,905

#### ANTINOZZI REPORT - OPERATING YEAR 2021-2022 (435 BUILDING PROJECTS)

\*Items moved from year 3 to year 2 are highlighted in red

eds	PRIORITY 4 125 Cafety														_	456.7
1	PRIORITY 1 - Life Safety				40.000										\$	156,73
1	Concrete repair at the entry of roof canopy to the boiler room			\$ \$	40,908										\$	40,9
2	Installation new interior cameras			\$	60,271					42.626					\$	60,2
1	Repair the cracked concrete steps and landing at Door 3								\$						\$	13,6
1	Remove guardrail and replace all stone coping outside north Door #22					_	20.202		\$	13,636					\$	13,6
1	Repair broken southwest brick wall at dumpster enclosure (Moved from 2022-2023 - Year 3)					\$	28,282								\$	28,2
	PRIORITY 2 - Educational Environment														\$	285,2
1	Replace bus bar for grounding for MDF and IDF rooms	\$	12,272			\$	12,272								\$	24,5
1	Replacement and installation AHU with dehumidifier			\$	11,879										\$	11,8
2	Replacement Air Compressor: 5 HP							\$ 6	,818						\$	6,8
2	Installation Packaged RTU: 5 ton							\$ 36	,110						\$	36,3
2	System controls bms Packaged RTU: 5 ton							\$ 11	,030						\$	11,0
2	Install ADA ramp from audience to stage in auditorium							\$ 22	,979						\$	22,
2	Installation Pipe railings, tube railings								\$	10,227					\$	10,2
2	Update electrical wiring for IT closets								\$	13,636	\$ 13,636				\$	27,2
1	Updating clock maintenance (Moved from 2022-2023- Year 3)	\$	5,656	\$	7,071	\$	7,071		\$	7,071					\$	26,
2	Scrape and painting rusting locker bottoms and bench supports in Locker Rooms (Moved from 2022-2023- Year 3)										\$ 24,924				\$	24
	Replacement Air Compressor: 3 HP with air dryer (Moved from 2022-2023- Year 3)					\$	10,227								\$	10
2	Interior painting in the auditorium												\$ 37,073		\$	37,0
2	Interior painting in the black box (Moved from 2022-2023- Year 3)												\$ 35,313	3	\$	35,3
	PRIORITY 3 - Building Envelope														\$	181,7
2	Replacement boiler feed tank pump	\$	30,681												\$	30,6
2	Bms system control for boiler tank pump	\$	5,727												\$	5,7
1	Replacement Cooling Tower pump 40 HP Base mounted	•	-,	\$	12,954										\$	12,9
1	Replacement Cooling Tower Pump			\$	2,864										\$	2,8
1	Replacement and updating cooling tower control			\$	11,454										\$	11,
3	New exterior planting			\$	17,045										\$	17,0
2	Louver and vents replacement near door 3 and 7 ( moved from 2022-2023 - Year 3)	\$	9,899		,										\$	9,
2	Remove and replacement air compressor and dryer for heat pump (moved from 2022-2023 - Year 3)	\$	17,676												\$	17,
2	Cleaning staining efflorescence mildew, gym, exterior, boiler room,(original building) (Moved from 2022-2023 - Year 3)					\$	13,636								\$	13,
2	Cleaning staining efflorescence mildew, exterior, second floor (Moved from 2022-2023 - Year 3)					\$	13,636								\$	13,6
2	Clean and restore brick and mortar outside stairwell egress Door #13 (Moved from 2022-2023 - Year-3)					\$	3,409								\$	3,4
2	Remove wood framing from around two (2) exhaust louver openings from Boiler Room's upper level (Moved from 2022- 2023- Year 3)					\$	17,045								\$	17,
1	Reseal exterior and interior sills of all existing perimeter windows at the greenhouse												\$ 3,322	2	\$	3,
1	Replacement of window gasketing and glazing in the greenhouse												\$ 22,396	5	\$	22,3
	Facilities Astinari Var 2 Parament dating		01 014		164 446	٠.	105 570	ć 7C	027 ^	F0 200	ć 20.560	ć	ć 00 404		<u>_</u>	633.
	Facilities Antinozzi Year 2 Recommendations	<u>;</u> >	81,911	>	104,446	<b>ب</b> ج	105,5/8	<b>&gt;</b> /6,	93/ \$	58,206	<b>&gt; 38,560</b>	<b>&gt;</b> -	\$ 98,104	,	\$	623,7

## WESTPORT PUBLIC SCHOOLS FIVE YEAR PROPOSED CAPITAL FORECAST - PRIORITY LISTING 2020-2021 (YEAR 1 OF 5)

FISCAL YEAR	DESCRIPTION	ESTIMATE	SUB-TOTAL	Antinozzi Report Year	* Priority
2020-2021	GREEN'S FARMS ELEMENTARY SCHOOL				
	Cooling Tower Replacement	\$213,000	\$213,000	2021	1
	Notes: A midwinter job. Cost estimate based on 2018 bid. We don't agree on price and timeframe.				
2020-2021	KINGS HIGHWAY ELEMENTARY SCHOOL				
	** Main entrance redesign including ADA access	\$98,483		2020	2
	** Installation ADA Stage access	\$52,524	\$151,007	2020	2
	Notes: Review of current ADA codes required.				
2020-2021	SAUGATUCK ELEMENTARY SCHOOL				
	** Replacement EPDM; single-ply membrane SW addition	\$1,191,075		2020	1
	** Replacement EPDM; single-ply membrane SW addition - auditorium	\$387,659		2020	1
	** Replacement EPDM; single-ply membrane NE addition	\$723,497		2020	1
	** Remove and replacement Flashing; marble roof coping NE addition	\$221,586		2020	1
	** Installation roof walkway pads to all major equipment and ladders in each roof replacement	\$62,635	\$2,586,452	2020	1
	Notes: Summer project (AIA/ roof design documents production starting in 2020, roof at the end of useful life)				
2020-2021	STAPLES HIGH SCHOOL				
	** Remove and replacement existing EPDM roofing system down to deck at portions of building	\$5,277,890	\$5,277,890	2020	1
	Notes: Summer project (AIA/ roof design documents production starting in 2020, roof at the end of useful life)				
	Total Fiscal Year 2020-2021 (without soft cost)		\$8,228,349		

Projected 11% Soft cost required for year 2020-2021 Projected 11% Soft cost required for upcoming year 2021-2022 \$881,688 \$571,314

**Grand Total Fiscal Year 2020-2021** (soft cost included)

\$9,681,351

<sup>\*</sup>Priority recommended by facilities department needs

<sup>\*\*</sup> Soft costs include engineering, architectural design and project management estimated at 11%

# WESTPORT PUBLIC SCHOOLS FIVE YEAR PROPOSED CAPITAL FORECAST - PRIORITY LISTING 2021-2022 (YEAR 2 of 5)

FISCAL YEAR	DESCRIPTION	ESTIMATE	SUB-TOTAL	Antinozzi Report Year	* Priority
2021-2022	COLEYTOWN ELEMENTARY SCHOOL				_
	New installation ductless split AC for IT closet	\$68,180	\$68,180	2021	2
	Notes: This must be coordinated in 2020 with IT dept and verify requirement to start project in 2021				
	RTU 3 AHU 5 Ton Main Office (This is a winter/spring job)	\$27,903			
	Building management control system component RTU-3 (This is a winter/spring job)	\$11,030	\$38,933	2020	2
	Notes: RTU 3 AHU 5 currently has useful life left in the system				
	** Asphalt Repair and Replacement (This is a summer job)	\$376,729	\$376,729	2021	2
	Notes: Pending analysis provided by StreetScan		·		
2021-2022	GREEN'S FARMS ELEMENTARY SCHOOL				
	New installation ductless split AC for IT closet	\$64,430	\$64,430	2021	2
	Notes: This must be coordinated in 2020 with IT dept and verify requirement to start project in 2021		· ·		
	** Asphalt Repair and Replacement (This is a summer job)	\$83,907	\$83,907	2020	2
	Notes: Pending analysis provided by StreetScan	, , , , , , ,	+		
2021-2022	LONG LOTS ELEMENTARY SCHOOL				
2021 2022	Updating Electrical Wiring IT closets	\$81,816	\$81,816	2021	1
		\$61,616	φοι,στο		
	** Remove and replace glazed structures in the art room	\$98,483	\$98,483	2020	2
	Notes: Pending design review with an architect				
	**Asphalt Repair and Replacement (This is a summer job)	\$397,512		2021	2
	**Asphalt Repair and Replacement (This is a summer job)	\$131,064	\$528,576	2020	2
	Notes: Pending analysis provided by StreetScan		·		
2021-2022	SAUGATUCK ELEMENTARY SCHOOL				
	** Repair Cast-in-Place Concrete At the secondary entrance at the end of the NE Addition	\$65,655	\$65,655	2020	2
	Notes: Requires masonary consultants to best define scope of work and aid with the bid preparation	ĺ	. /		

	** Remove and replace spalling bricks on 5% of brick facades, Repointing; cracks mortar; sealant  ** Re-mortar significant building settlement cracking on interior brick walls  ** Remove black stains; efflorescence; mildew  ** Repointing; cracks, spalling on the front facade (Cafeteria)  Notes: Requires masonary consultants to best define scope of work and aid with the bid preparation	\$197,690 \$21,212 \$96,021 \$63,408	\$378,331	2020 2022 2020 2021	2 2 2 2 2 2
	** Asphalt Repair and Replacement (This is a summer job)	\$392,443	\$392,443	2020	2
	Notes: Pending analysis provided by StreetScan				
2021-2022	BEDFORD MIDDLE SCHOOL Redesign and upgrade of four(4) Science Labs, Notes: Moved from FY19-20, academic master plan required, curriculum delivery input needed	\$320,000	\$320,000		3
	** Repair structural concrete slab- on-grade in corridor outside the Main Office to the end of the Auditorium  ** Repair structural concrete slab- on-grade in receiving/mechanical corridor and Auditorium seating areas  ** Maintenance of Unit Masonry - Restoration in gym and near door 11,13  ** Repair and replace of ceramic of popping ceramic tiles in the locker room	\$88,635 \$40,781 \$47,726 \$25,568	\$202,710	2020 2020 2021 2021	2 2 2 2
	Notes: Require masonary consultants to best define scope of work and aid with the bid preparation		, , ,		
	New installation ductless split AC for IT closet  Notes: This must be coordinated in 2020 with IT dept and verify requirement to start project in 2021	\$68,180	\$68,180	2021	2
	Replacement "floating" CV actuators for VAV boxes  Notes: Assistant of control humidity	\$170,451	\$170,451	2021	2
	**Asphalt Repair and Replacement (This is a summer job)  **Asphalt Repair and Replacement (This is a summer job)  Notes: Pending analysis provided by StreetScan	\$263,034 \$243,178	\$506,212	2020 2020	2 2
	**Concrete paving repair and replacement  **Concrete paving repair and replacement  Notes: Further investigation required to define scope of work	\$43,700 \$51,894	\$95,594	2020 2020	2 2
2021-2022	STAPLES HIGH SCHOOL  **Investigate, patch and repair causes of cracking in floor slab in the auditorium	\$90,336	\$90,336	2021	2
	**Replacement acoustical ceiling tiles at lower level corridor	\$674,319	\$674,319	2021	2
	**Removal existing poured sports flooring and replace with seamless Pulastic Classic 110	\$1,203,586	\$1,203,586	2021	1

Notes: May require extended closure of the field house due to remediation, pending environmental analysis				
**Remove and replacement in Area A: Small Indoor AHU's	\$165,678		2021	2
**Installation bms system controls for Area A: Small Indoor AHU's	\$34,363	\$200,041	2021	2
Remove and replacement Pool Dehumid AHU	\$102,271		2021	2
**Installation bms system controls for Area A: Pool Dehumid. AHU	\$17,181	\$119,452	2021	2
Installation ductless split for IT closets : 2 tons	\$68,180		2021	2
Installation ductless split for IT closets: 5 tons	\$37,499	\$105,679	2021	2
Notes: This must be coordinated in 2020 with IT dept and verify requirement to start project in 2021				
**Asphalt Repair and Replacement (This is a summer job)	\$144,562	\$144,562	2021	2
Notes: Pending analysis provided by StreetScan				
Total Fiscal Year 2021-2022 (without soft cost)		\$6,078,605		

Projected 11% Soft cost required for upcoming year 2022-2023

\$1,132,274

Gran Total Fiscal Year 2021-2022 (softcost included)

\$7,210,879

<sup>\*</sup>Priority recommended by facilities department needs

<sup>\*\*</sup> Soft costs include engineering, architectural design and project management estimated at 11%